

DEBRIS SHIELD

Assembly Diagram

**The Debris Shield is ONLY for use with the P.A. Torch manufactured by Burners, Inc.*



1. Insert your [P.A. Torch](#) through U-Bolt and Torch Head Cut Out in your [Debris Shield](#)
2. Tighten U-Bolt to secure your [Debris Shield](#) to your P.A. Torch Head
3. Front shield may be raised/lowered to operators' preference by adjusting screws on both sides of your Debris Shield.

U.S. Veteran Owned & Operated
burners, inc.
Combustion Technology and Custom Metal Fabrication

PO Box 735 • Milford • MI 48381
800-878-2876 • info@burnersinc.com
www.burnersinc.com